



EFFECT OF SERVICE LIQUID TEMPERATURE ON THE CAPACITY OF LIQUID RING VACUUM PUMPS



RIF. - Ref.: F.P./C.T.

SOSTITUISCE - Replaces: 6300 - 6500.583.01.01

DATA - Date: GIUGNO 96 - June 96

N°. : 9300.583.01.02